



Fig. 3.1. Volet (élévation intérieure / avant restauration)



Fig. 3.2. Fenêtre (élévation ext. / avant restauration)



Fig. 3.3. Volet (élévation extérieure / avant restauration)



Fig. 3.4. Volet (élévation ext. / après restauration)



Fig. 3.5. Charnière inférieure (détail)

LIGNOL (Morbihan)		
Manoir de Kerduel		
Planche n°3 - Volet		
A. TIERCELIN	1998	Etude n°56002



1

2



3

4



5

6

7

8

9

10



11

12

13

14

15



16 17 18 19

20 21 22 23 24 25 26 27 28 29 30

31 32 33 34 35 36 37 38 39 40

41 42 43 44 45 46 47 48 49 50

51 52 53 54 55 56 57 58 59 60

61 62 63 64 65 66 67 68 69 70